COPY / OF (

I-28-200532- 8

Copy 8 of 9 copies

673

2 April 1968

This document contains

4 pages.

EVALUATION SUMMARY

Mission C-058C

1. Processing and Titling - Good/Field

2. Physical Condition - Good

3. Hypo Retention Negligible

4. Exposure (based on density) - Medium

5. General Comments:

- A. Drying marks on emulsion on all parts of 9L and 9R.
- B. Emulsion rub on all parts head to tail of 9L and 9R.
- C. Intermittent title transfer noted on all parts of 9L and 9R.
- D. A few kinks, pinholes and embedded dirt on all parts of 9L and 9R.

MISSION NO. C-058C EVALUATION REPORT

| Evaluated By | Q.C. | | Camera | 9L/9R/Tracker |
|---------------------|-------------|------------|----------|----------------|
| Evaluation Date | 21 March 19 | 068 | Emulsion | 3401/3401/3404 |
| Film Metering | | Good | | |
| Film Tracking | | Good | | |
| Vacuum Failure | | None | | |
| Clock Operation Exp | osure | Good | | |
| Counter Operation | | Operationa | 1 | |
| Data Chamber (image | quality) | Good. | | |
| Apparent Resolution | | Normal | | |
| Apparent Granularit | у | Normal | | · |
| Density | | Medium | | |
| Contrast | | Medium | | |

Discrepancies: 9L

| Part | Frames | <u>Comments</u> |
|------|-------------------------------------|---|
| 1 | 1-10 80-81 103-104 132-133 | Intermittent base scratch Splice |
| 2 | 134-266 236-237 | Emulsion scratches Splice |
| 3 | 267-399 343-344 369-370 | Intermittent emulsion scratch Splice |
| 4 | 502 - 503 | Splice |
| 5 | 628 635-636 664 | Emulsion dig Splice Lacquer in format |
| 6 | 742-743 | Splice |
| 7 | 901 - 902 902 | Splice Emulsion dig |

Page 2

Discrepancies (Cont'd) 9L Camera

| Part | Frames | Comments |
|-----------|---|--|
| 8 | 932 1034-1035 | Moisture spot Splice |
| 9 | 1160-1161 | Splice |
| 10 | 1198-1200 1300-1301 | Base scratches Splice |
| 11 | 1433-1444 | Splice |
| 12 | 1566-1568 | Splices |
| 13 | 1699-1700 | Splice |
| 14 | 1782 1832 -1 833 | Base scratches Splice |
| 15 | 1933,1965-1966 | Splice |
| 9R Camera | <u>a</u> | |
| 1 | 1-33 1-84 103-104 122-123 132-133 | Intermittent static titled edge Base scratch Splice |
| 2 | 134-266 236-237 257 | Intermittent static titled edge Splice Lacquer smear |
| 3 | 368 369-370 392-393 399 | Emulsion scratch Splice ** Emulsion pickoff |
| 4 | 503 502 - 503 | Emulsion pickoff Splice |
| 5 | 595,631 600 635-636 | Emulsion pickoff Lacquer smear Splice |
| 6 | 768 - 769 787 - 788 | Splice |
| 7 | 867-868,914-915 921-923 799-931 901-902 905 | Moisture spot Intermittent emulsion scratch Splice Ferrotyping spot |

Page 3

Discrepancies (Cont'd) 9R Camera

| <u>Part</u> | Frames | Comments |
|-------------|--|--|
| 8 | 952,963,967-968 1034-1035 | Moisture spot Splice |
| 9 | 1136-1140 | Moisture spot |
| 10 | 1212,1232,1235, 1293,1312,1313, 1324,1325 1300-1301 | Moisture spot Splice |
| 11 | 1331 1372 1396 1433-1434 1331-1463 | Crease Emulsion scratch Ferrotyping Splice Intermittent moisture spot |
| 12 | 1469,1494,1505, 1556,1578,1579 1566,1567 | Moisture spot Splice |
| 13 | 1608-1609, 1699-1700 1642 1702 | Splice Emulsion pickoff Lacquer smear |
| 14 | 1730-1862 1740 1744,1832-1833 1833 | Intermittent static on titled edge Lacquer smear Splice Emulsion digs |
| 15 | 1865,1868,1902, 1971,1981 | Moisture spot |
| Tracker 1 | Record (35mm film | type 3404) |
| | 1 | Kink |
| | 1-383 | Intermittent dirt, intermittent base and emulsion scratches |
| | 158 | Pinholes |